

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.


**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

JAMES B. HOLLAND
CUSTOMER NUMBER: 40228 1/3



FRONT SIDE OF HANDKERCHIEF VALET = HV

DRAWING FIG. 1




JAMES B. HOLLAND
CUSTOMER NUMBER: 40228

2/3

BACK SIDE OF HANDKERCHIEF VALET = HV = A


DRAWING - FIG. 2



VC/DSAT = VELCRO
OR DOUBLE-SIDED
ADHESIVE TAPE

A VC/DSAT
ATTACHED
TO BACK SIDE
OF HV
3 3/4" x 1"
H W

B VC/DSAT
ATTACHED
TO FRONT SIDE
OF ET
3 1/4" x 1"
H W

 = OUTLINE OF
VC/DSAT

JAMES B. HOLLAND
CUSTOMER NUMBER: 40228 3/3

RIGHTSIDE END VIEW OF HV

DRAWING-FIG. 3

